

INTRODUCTION

This Job Aid, *26" DEEP SIDE-BY-SIDE REFRIGERATOR/FREEZERS*, (Part No. 4321940), and the companion video tape, *26" DEEP SIDE-BY-SIDE REFRIGERATOR/FREEZERS*, (Part No. 4321970), provides specific information on for the installation, service and repair of 20 cu. ft. side-by-side refrigerator/freezers with 26" deep cabinets.

26" DEEP SIDE-BY-SIDE REFRIGERATOR/FREEZERS has been compiled to provide the most recent information on design, features, troubleshooting, service and repair procedures. Whirlpool required sweep charge procedures are to be strictly adhered to when repairing the sealed system. For a complete explanation of those procedures, refer to the Job Aid, *SWEEP CHARGE PROCEDURES FOR THE 90's*, (Part No. 4321717) and its companion video (Part No. 4321718.)

GOALS AND OBJECTIVES

The goal of this Job Aid is to provide detailed information that will enable the service technician to properly diagnose malfunctions and repair 22 cu. ft. side-by-side refrigerator/freezers with 26" deep cabinets.

The objectives of the Job Aid are:

The service technician will -

- Understand proper safety precautions.
- Follow proper refrigerant recovery procedures.
- Successfully troubleshoot and diagnose malfunction.
- Successfully perform necessary repairs.
- Successfully return the refrigerator/freezer to proper operational status.

TO THE INSTRUCTOR/INDEPENDENT STUDENT

At the end of certain sections of this Job Aid you will find a "Confirmation of Learning Exercise." A symbol that looks like this (\) indicates that a pencil and two "Hi-Light" markers may be necessary to complete the exercise. Certain exercises may require that service procedures be performed if an appropriate appliance is available.



WHIRLPOOL CORPORATION ASSUMES NO RESPONSIBILITY
FOR ANY REPAIRS MADE ON OUR PRODUCTS BY ANYONE
OTHER THAN AUTHORIZED SERVICE TECHNICIANS.